

**DEPARTMENT OF TRANSPORTATION****DIVISION OF ENGINEERING SERVICES****OFFICE ENGINEER**1727 30<sup>th</sup> Street MS-43

P.O. BOX 168041

SACRAMENTO, CA 95816-8041

FAX (916) 227-6214

TTY 711

*Flex your power!  
Be energy efficient!*

November 7, 2012

12-Ora-91-0.9/5.4

12-OC5704

Project ID 1200000079

## Addendum No. 1

Dear Contractor:

This addendum is being issued to the contract for CONSTRUCTION ON STATE HIGHWAY IN ORANGE COUNTY IN ANAHEIM AND FULLERTON FROM 0.3 MILE WEST OF BROOKHURST STREET TO 0.2 MILE EAST OF STATE COLLEGE BOULEVARD AND NEAR ANAHEIM AT ROUTE 55/91 SEPARATION AND IN IRVINE AT THE TRAFFIC MANAGEMENT CENTER AT 6681 MARINE WAY.

Submit bids for this work with the understanding and full consideration of this addendum. The revisions declared in this addendum are an essential part of the contract.

Bids for this work will be opened on Thursday, November 29, 2012.

This addendum is being issued to revise the Notice to Bidders and Special Provisions.

In the Special Provisions, Section 2, "BIDDING," is revised as attached.

In the Special Provisions, Section 5-1.20H, "Private Property Coordination," the second paragraph is revised as follows:

"Begin work within Work Around Area A (parcel nos. 102725-1 and 102725-2) after April 24, 2013."

In the Special Provisions, Section 5-1.20H, "Private Property Coordination," the sixth paragraph is revised as follows:

"Begin work within Work Around Area E (parcel nos. 102769-1, 2 and 102770-1, 2) after February 28, 2013."

In the Special Provisions, Section 59, "PAINTING," is revised as attached.

Addendum No. 1  
Page 2  
November 7, 2012

12-Ora-91-0.9/5.4  
12-0C5704  
Project ID 1200000079

To Bid book holders:

Inquiries or questions in regard to this addendum must be communicated as a bidder inquiry and must be made as noted in the Notice to Bidders section of the Notice to Bidders and Special Provisions.

Indicate receipt of this addendum by filling in the number of this addendum in the space provided on the signature page of the Bid book.

Submit bids in the Bid book you now possess. Holders who have already mailed their book will be contacted to arrange for the return of their book.

Inform subcontractors and suppliers as necessary.

This addendum and attachments are available for the Contractors' download on the Web site:

**[http://www.dot.ca.gov/hq/esc/oe/project\\_ads\\_addenda/12/12-0C5704](http://www.dot.ca.gov/hq/esc/oe/project_ads_addenda/12/12-0C5704)**

If you are not a Bid book holder, but request a book to bid on this project, you must comply with the requirements of this letter before submitting your bid.

Sincerely,



REBECCA D. HARNAGEL

Chief, Office of Plans, Specifications & Estimates

Office Engineer

Division of Engineering Services

Attachments



## 59 PAINTING

**Add to section 59-2.01A:**

Clean and paint the structures shown in the following table:

Bridge name and number	Work description
North Anaheim OH Bridge No. 55-0216 Acacia Street UC Bridge No. 55-0218	Paint bridge widening including painting new steel members, blast cleaning locations for attaching new steel to existing members, and undercoating and finish coating all surfaces

**Replace "Reserved" in section 59-2.01C(2) with:**

Submit proof of certification under the SSPC-QP Certification Program with your bid. Required certifications are as follows:

1. SSPC-QP 3, Enclosed Shop Facility or AISC Sophisticated Paint Endorsement Quality Program, P1-Enclosed

**Add to section 59-2.01D(1):**

Instead of certification complying with SSPC-QP 1, you may submit documentation with the painting quality work plan showing compliance with the requirements in section 3 of SSPC-QP 1.

Instead of certification complying with SSPC-QP 2, you may submit documentation with the painting quality work plan showing compliance with the requirements in sections 4.2 through 4.4 of SSPC-QP 2, Category A.

**Add to section 59-2.03A:**

For existing structural steel at bridge no. 55-0216 and 55-0218, paint removal is not required at contact surfaces for connections to new structural steel. Clean these contact surfaces under SSPC-SP-1.

**Add to section 59-2.03B(2)(a):**

Clean inside surfaces of bolt holes under SSPC-SP-1 and remove visible rust.